

Tanker Structure and Hull Failure Strength

Hajime Kawano and Masaru Hirakata,
National Maritime Research Institute, Japan.

Contents;


- ◆ **1 .Introduction**
 - ◆ 1 - 1. Large-scale oil spill accident by tankers
 - ◆ 1 - 2. IMO rule movement on tanker structure
- ◆ **2 .Aging effect of ship hull**
 - ◆ 2 - 1. Typical strength degradation by aging
 - ◆ 2 - 2. Hull plate corrosion data properties
 - ◆ 2 - 3. Degrading of longitudinal bending strength
- ◆ **3 .Failure strength of aging tanker hull**
 - ◆ 3 - 1. Basic mechanism of large-scale hull failure
 - ◆ 3 - 2. Case study
- ◆ **4 .Conclusion**

1-1 .Large-scale oil spill accident by tankers

year	ship name	flag state	volume (10 ³ kL)	causes
1967	“Torrey Canyon”	Liberia	119	grounding
1972	“Sea Star”	Korea	120	collision & fire
1976	“Urquiola”	Spain	100	grounding
1977	“Hawaiian Patriot”	Liberia	95	<u>foundered at 12yrs</u>
1978	“Amoco Cadiz”	Liberia	223	grounding
1979	“Atlantic Empress”	Greece	287	collision & fire
1979	“Independenta”	Rumania	95	collision & fire
1983	“Castillo de Bellver”	Spain	252	fire
1988	“Odyssey”	Greece	132	<u>foundered at 17yrs</u>
1989	“Exxon Valdez”	USA.	37	grounding
1991	“ABT Summer”	Liberia	260	Fire
1993	“Braer”	Liberia	85	grounding
1996	“Sea Empress”	Liberia	72	grounding
1997	“Nakhodka”	Russia	6.2	<u>foundered at 26yrs</u>
1999	“Erika”	Malta	10 + α	<u>foundered at 25yrs</u>
2001	“Baltic Carrier”	Marshall Is.	2.5	collision & fire
2002	“Prestige”	Bahama	(4)??	<u>foundered at 26yrs</u>

1-2. IMO rule movement on tanker structure

History in VLCC structural changes (1)



1-2. IMO rule movement on tanker structure

History in VLCC structural changes (2)

Tanker structural regulation by IMO

1954: OILPOL adopted (海洋汚濁防止条約)

1969: Load on top (LOT) system

1971: Tank size limitation

1973: Segregated ballast tank (SBT)

Damage stability

1978: MARPOL 73/78 13E. SBT protective location (PL)


IGS / COW requirement

1992: MARPOL 73/78 13F. Double-hull tanker for new ship

ditto 13G. Existing ship phase out schedule

Alteration of Tank Arrangement


1: Pre-MARPOL (Single Hull)




2: Pre-MARPOL with Tank Size Limitation (Single Hull)



3: MARPOL '73 & '78 (Single Hull)



4: MARPOL '92 (Double-hull)




1-2. IMO rule movement on tanker structure *Enhanced Survey Program on tanker structure*

Guideline on “Enhanced Survey Program”

IMO resolution A.744 (18)

SOLAS chapter XI, regulation 2

- 1) Survey program worked out in advance
- 2) Dry-dock survey
- 3) Overall survey
- 4) Close-up survey
- 5) Thickness measurement
incl. belt gauging. →→→→
- 6) Corrosion preventive system (coating)
- 7) survey report file on board



1-2. IMO rule movement on tanker structure

Phase out of single hull tankers

MEPC46 revision to MARPOL regulation 13G.

Category of tanker (crude and dirty oil)	New phase out schedule
Category-1 Non-double hull (Pre-PL/SBT) oil tankers Built before 1982 20,000 DWT and above	Withdrawn between 2003 - 2007 Beyond 2005, CAS requirement
Category-2 Non-double hull (PL/SBT) oil tankers Built during 1982 ~ 1996 20,000 DWT and above	Withdrawn between 2003 - 2015 by arriving at 25 years of age Final use 2015 Beyond 2010, CAS requirement
Category-3 Non-double hull oil tankers 5,000~20,000 DWT	Withdrawn between 2003 - 2015 Final use 2015

(Note) CAS; Condition Assessment Scheme

2. Aging effect on ship hull

2-1. Typical strength degradation by aging

(1) Corrosion

- a. Corrosion in frame member
- b. Corrosion in plating
- c. Local corrosion

(2) Fatigue crack

(3) Degradation of paint coating


2-1. Typical strength degradation by aging(1)

(1) Corrosion

- a. Frame corrosion
- b. Plating corrosion
- c. Local corrosion

(2) Fatigue crack



(3) Coating degradation



Corrosion wastage in deck longitudinal of WBT, with poor fillet weld and sharp edge at depth end. (aged 15 years)

2-1. Typical strength degradation by aging(2)

- (1) Corrosion
 - a. Frame corrosion
 - b. Plating corrosion
 - c. Local corrosion
- (2) Fatigue crack
- (3) Coating degradation



- Corrosion in bottom plating ;**
- 1) horizontal/vertical plating
 - 2) splashed zone or not
 - 3) effect of fluid velocity
 - 4) effect of high temperature, etc

sea water


sea water

2-1. Typical strength degradation by aging(3)


- (1) Corrosion
 - a. Frame corrosion
 - b. Plating corrosion
 - c. Local corrosion
- (2) Fatigue crack
- (3) Coating degradation

- * pitting corrosion
- * raised by high stresses
- * grooving corrosion , etc.

Typical local corrosion on stringer: below






grooving corrosion along fillet weld of deck longl.



2-1. Typical strength degradation by aging(4)

- (1) Corrosion
 - a. Frame corrosion
 - b. Plating corrosion
 - c. Local corrosion
- (2) Fatigue crack
- (3) Coating degradation

Fatigue crack at side longitudinal, in 2nd generation VLCC damages.




Fatigue crack growth at fillet welded corner.



2-1. Typical strength degradation by aging(5)



Stress vs. strain curve of aging plate;

- Cut-out and flushed specimen shows no less ability to virgin plate.
- Apparent drop in S-S curve for aging plate is by surface roughness due to corrosion.



2-1. Typical strength degradation by aging

Degradation tendency with increase of ship age



(a) Trend in degradation mode

(b) Trend in number of failures

2. Aging effect of ship hull


2-2. Hull plate corrosion data properties

Corrosion rate analysis by using class NK database

Structural Member			50% level				95% level				
			Tk.	5yrs.	10yrs.	15yrs.	20yrs.	5yrs.	10yrs.	15yrs.	20yrs.
Upper Deck Plate			COT	0.00	0.52	1.03	1.33	0.82	1.93	2.63	3.14
"			WBT	0.00	0.00	0.79	1.06	0.51	1.15	1.59	1.92
Deck Longitudinals			COT	0.00	0.34	0.82	1.06	0.51	1.21	1.64	1.95
"			WBT	0.00	0.00	0.63	0.96	0.00	0.99	1.46	1.82
Bottom Plate			COT	0.00	0.74	1.16	1.43	1.02	2.11	2.78	3.27
"			WBT	0.00	0.00	0.88	1.28	0.30	1.53	2.35	2.96
Bottom Longl.	Web	COT	0.00	0.00	0.68	1.00	0.27	1.04	1.50	1.85	
		WBT	0.00	0.00	0.68	1.00	0.00	1.03	1.50	1.85	
"	Flange	COT	0.00	0.00	0.77	1.01	0.59	1.24	1.64	1.94	
		WBT	0.00	0.00	0.53	0.91	0.00	0.93	1.40	1.77	
Side Shell Plate			COT	0.00	0.00	0.78	1.03	0.44	1.16	1.60	1.92
"			WBT	0.00	0.00	0.69	1.20	0.00	1.11	1.66	2.09
Side Longl.	Web	COT	0.00	0.00	0.59	0.94	0.29	1.02	1.46	1.81	
		WBT	0.00	0.00	0.44	0.87	0.00	0.97	1.41	1.76	
"	Flange	COT	0.00	0.00	0.58	0.94	0.00	0.98	1.44	1.80	
		WBT	0.00	0.00	0.48	0.89	0.00	0.92	1.39	1.75	
Longitudinal Bhd.Plate			COT	0.00	0.00	0.84	1.10	0.55	1.19	1.63	1.96
"			WBT	0.00	0.33	0.81	1.04	0.56	1.24	1.65	1.95
Longi.Bhd.Longl.	Web	COT	0.00	0.00	0.54	0.92	0.27	1.01	1.45	1.79	
		WBT	0.00	0.00	0.54	0.92	0.25	1.01	1.44	1.79	
"	Flange	COT	0.00	0.00	0.62	0.96	0.34	1.04	1.48	1.82	
		WBT	0.00	0.00	0.44	0.94	0.00	0.97	1.75	2.45	

2-2. Hull plate corrosion data properties (2)

- example for deck structure -




Allowable diminution Level by Class Society spec.

Allowable diminution level for uniform corrosion

Structural Member	Allowable Diminution Level
<ul style="list-style-type: none"> -Shell plates -Strength deck plates -Slab longls on shear strake and stringer plate of strength deck -Tight bulkheads in deep tanks -Inner bottom plates 	20% of original thickness + 1 mm
<ul style="list-style-type: none"> -Floors and girders in double bottom -Primary members (web & face) -Web, face and bracket of hold frames -Watertight bulkhead plates 	25% of original thickness
<ul style="list-style-type: none"> -Web, face and bracket of frames (excluding hold frames), longitudinal beams and stiffeners -Effective deck plates -Hatch cover and hatch beam 	30% of original thickness

2-2. Hull plate corrosion data properties

Schematic diagram on aging ship strength




2. Aging effect of ship hull

2-3. Reduction in mid-ship section modulus

Estimated results on average tendency of the VLCC mid-ship section modulus;


- (1) IMO requirement :
within 10% loss of Z
- (2) Average corrosion damage is within IMO requirement.

Note:
— analyzed
---- imaginary scatter



3. Failure strength of aging tanker hull

3-1. Basic mechanism of large-scale hull failure



3-1. Basic mechanism of large-scale hull failure *As to hull break-up mode*

Trigger element for tanker hull break-up ;

- (1) Buckling/collapse at Deck structure in Sagging
- (2) Crack propagation at Bottom structure in Sagging
- (3) Crack propagation at Deck structure in Hogging
(multi-site damage)
- (4) Buckling/collapse at Bottom structure in Hogging
 - i) break-up occurs in high wave ; Sagging M. > Hogging M.
 - ii) deck back surface is the most severe corrosive space in hull circumstances, and so forth.


3-2. Case study

Outline of the Nakhodka casualty

Date: 1977.1.02, 02:40am


Location: Okino-shima NNE 106km

wave condition: $H_{1/3}$ 8m, T_{ave} 9 sec



General Arrangement of the MS Nakhodka

Fr.137 Fr.153
Failed and broke in two



Fractured cross-section of hull girder at sea bottom

3-2. Case study

Loading pattern at the Nakhodka casualty

**Loading pattern at the casualty ;
excess to a standard loading pattern**

No.5 P.W.T. 0 (0)	No.4 P.W.T. 1,300 (618.5)		No.3 P.W.T. 1,307 (1,420)		No.2 P.W.T. 1,263 (0)		No.1 P.W.T. 440 (408.5)	
No.9 C.T. 590 (1,543)	No.8 C.T. 1,417 (1,543)	No.7 C.T. 1,432 (1,543)	No.6 C.T. 1,418 (1,543)	No.5 C.T. 1,416 (1,543)	No.4 C.T. 1,372 (1,543)	No.3 C.T. 1,370 (1,581)	No.2 C.T. 1,345 (1,581)	No.1 C.T. 88 (921)
No.5 S.W.T. 0 (0)	No.4 S.W.T. 1,302 (618.5)		No.3 S.W.T. 1,301 (1,420)		No.2 S.W.T. 1,257 (0)		No.1 S.W.T. 601 (408.5)	

Loading Patterns

values : Load (in kI) at the casualty
() indicates a standard condition.

3-2. Case study

Corrosion wastage at the Nakhodka casualty


**Measurement result ;
20-35% of plate thickness reduced due to corrosion**

Structural member	Original thickness	Thickness reduction	Remarks
Bottom plate	20 mm	6 mm	based on the average of measured data around Fr. 157
Side shell	17 mm	6 mm	measured data are limited, and considered to be the same as bottom plating
Deck plate of center tank	20-24 mm	4 mm	based on the measured data in 1993
Deck plate of side tank	20-24 mm	7.5 mm	based on the average of measured data
Deck longitudinal	14 mm	5.5 mm	based on the average of measured data
Other members	11-14 mm	3 mm	measured data are scattering between 2 mm and 4 mm

3-2. Case study

Applied force at the Nakhodka casualty

VBM and VSF were obtained by using non-linear ship motion and response simulation software.




**Still water shearing force and bending moment
for the Nakhodka**

(solid line : at the accident, dotted line : standard condition)


3-2. Case study

Simulation cal. on ultimate collapse of Nakhodka

**Simulation result showed ;
the break-up started at the deck structure on about Fr.153.**




(a) collapse mode at deck



(b) stress at deck vs. time in simulation

3-2. Case study

Estimated results on load and strength



Section Modulus at the accident

Location	Section modulus at the time of accident	
	SS 6.2	SS 6.9
Deck	80,000 cm ² m	67,800 cm ² m
Bottom	67,000 cm ² m	68,500 cm ² m

Causes of the Nakhodka casualty;

- (1) *Excessive corrosion* made the Nakhodka's vertical bending strength about one half to that of as built.
- (2) So, the most *severe wave load* in a year at Japan sea, let her broke up.
- (3) In addition to the above, the *non-standard loading pattern* at the accident had enlarged the wave load.

4. Conclusions

- (1) Large-scale oil spill from tankers were not yet exterminated. And one critical factor must be hull excessive corrosion that might be overlooked, so that it should be strongly required strict implementation of the ESP and excluding sub-standard tankers.**
- (2) From the analysis of corrosion measurement data at the classNK inspections, not only average wastage rate but also increase of standard deviation of the rate are key factors to understand the ship ageing and the influence.**
- (3) As to hull breaking up, it seems that excessive corrosion and severe wave condition are two main players and a possible trigger failure might be a buckling/collapse of deck structure at the time of high wave of sagging.**

In anyway more actions are necessitated, not only to prevent casualties but also to mitigate the oil outflow and the damage of the ocean, to keep our global environment clean.